

INSPECTION REPORT  
ON

Shadow Lake Dam

- 1. Date of inspection 5/20/52
- 2. Water conditions level below crest

GENERAL DATA:

- 3. Location of dam Town of Glover
- 4. Owner and operator Barton Village
- 5. Characteristic features of dam embankment with masonry head wall - spillway section, sluiceway - 8' to crest
- 6. Other related data Pond area = 188 acres  
Volume = 30,000,000 cu.ft. D.R. = 5 mm (PSC case file 1488)

OBSERVATIONS:

- 7. Condition of structure embankment stable - concrete + masonry in good condition
- 8. Condition of equipment satisfactory
- 9. Operation maintain max pond level for campers
- 10. Maintenance Poor

REMARKS:

Village acquired dam in a foreclosure sale.  
has no special purpose for the structure

Inspected by JWA